

April 12, 2018

As a result of a failed BPF test. TBUSA is withdrawing the following bats from play. The bats listed do not meet the BPF. The two bats listed will be added to the TBUSA not eligible for play bat list attached under TBUSA Rules effective immediately. Any Bat not meeting the 1.15 BPF is not eligible for play.

Dirty South Bat Company

The Dirty South Bat Company, LLC has withdrawn its **Kamo Model BB KA 8** (30/22, 31/21, 32/22, 31/23, 32/24 only - pictures shown below). Dirty South will review the test results and the BPF compliance of this Model to determine if this withdrawal will be permanent. All customer inquiries should be directed to info@dirtyouthbats.com.



Wilson Company / DeMarini

DeMarini baseball bat Model 2¾" DeMarini 2018 CF Zen CBZ (32/-10 and 31/-10 only) have been suspended from TBUSA play. Wilson/DeMarini will have the opportunity to prove that this withdrawal should be lifted. If standards are met for such Model then the bat would be removed from the not eligible for play list.

The illegal bat use by a player will result in the both the head coach and the player who used the illegal bat be **EJECTED** from the game in progress. The illegal bat has to be discovered before the next pitch to a batter of either team. If the bat is deemed illegal by the umpire and/or Tournament Director, the defensive coach has the choice of the batter being called out and all players return to base prior to the at bat or take the play.